3/07/01 Dimas OK-I que do The 2 boyes in the brown boyes are new, but neither Tou descrapble !! Have tul until On gry headed & bug light! The me in the white boy has ber working i are gapudder just Otopped. Did Trot eur These with it Sie ne Know, Muigh 0Ab341960 @ Yahoo. com

EVIDENCE # 1A PACKAGE #1

AT&T BROADBAND CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS No serial # available			
Account	# 43747-04	Converter #				
Name: Joe Amaro / Dimas Amaro Address: 333 Cohannet Street		Converter Type:	Clear Max 3000 UPS pursuant to warrant on			
		Received From:				
	<u> </u>		3/9/01			
City:	Taunton	State/Zip	Ma. 02780			
SSN#:		Generated From:				
!	Pre 4	PPV Movies <u>YES</u> Point Test				
OTHER	NOTABLE FEATURES					
:						
:	CONVERTER APPEARANCE		RTER APPEARANCE			
<u>P</u>	Security Tabs Missing ADP Module Forced Open					
<u>R</u>	Outside Screws Missing U ADP Module Cover Missing Converter Damaged N Scretches/Medicage Very China					
<u>A</u>	Marks Around Outside Security					
T	Wires Cut	Jumper Wires Sti				
E	Tampered Codes	T Scratches/Marks on Legs of Key Chips				
	-	Missing Prom#				
· · · · · ·						
		oint Test	· A			
1.	Testing Point	Codes/Comments	Pass/Fail			
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	U N/A			
2.	Converter has 210 code or higher	I	N N/A			
3.	Converter has H-1 or H6 code, or tunes	R	I N/A			
4.	01-99 or 01-128 consecutively.		1 IV/A			
	Converter does not initialize (i.e. an addressable hit)	ATE	T N/A			
Of the 4 pc	oints, how many points does it have?	N/A				
Test Compl		N/A				
Date Completed On:		Special Project Auditor Paul Marmelo				
Comments:		June 25, 2001				
omments.		Confirmed Pirate Device	(decoder)			
OR OFFI	ICE USE ONLY:					
CONVERTER I		BY				
CONVERTER R	REMOVED 3/9/01	Y TAUNTON POLICE DEPAR				
COOKE - TT-		Y TAUNTON POLICE DEPAR	RTMENT			
CCOUNT HIS	STORY SUMMARY	TAGNION POLICE DEPAR	RIMENT			

EVIDENCE # 1B PACKAGE #1

AT&T BROADBAND CONVERTER TEST FORM

Date	3-9-01 Corp. #		<u>I-COMS</u>			
Accour	43747-04	Converter #	004101587 <u>VM4000</u>			
Name:	Joe Amaro / Dimas Amaro	Converter Type:				
Addres	s: 333 Cohannet Street	Received From:	UPS pursuant to warrant on			
		•	3/9/01			
City:	Taunton	State/Zip	Ma. 02780			
SSN#:		Generated From:				
						
		PPV Movies <u>YES</u>	-			
CODES	RECEIVED	Point Test				
	î					
OTHER	NOTABLE FEATURES					
	E CONVERTER APPEARANCE	INSIDE CONVER	TER APPEARANCE			
<u>P</u>	Security Tabs Missing	ADP Module Forced Open				
<u>I</u> <u>R</u>	Outside Screws Missing	U ADP Module Cover Missing				
<u>A</u>	Converter Damaged Marks Around Outside Screw	N Scratches/Marks on Key Chips				
<u>T</u> .	Wires Cut	I Jumper Wires Still In Place				
<u>E</u>	Tampered Codes	Scratches/Marks on Legs of Key Chips				
	- Imports Codes	Missing Prom #	•			
		oint Test				
1.	Testing Point	Codes/Comments	Pass/Fail			
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u> </u>			
2.	Converter has 210 code or higher	Ī	N			
3. :	Converter has H-1 or H6 code, or tunes	<u>R</u>	I			
4.	01-99 or 01-128 consecutively. Converter does not initialize (i.e. an	ATE				
	addressable hit)	MIL .	Ī			
0647 4						
	points, how many points does it have?					
i	pleted By:	Special Project Auditor Pa	ul Marmelo			
	June 25, 2001					
Commen	is:	Confirmed Pirate Device (decoder)			
OP OF	PICE LISE ONLY					
!	FICE USE ONLY:		, .			
		BY				
CONVERTER REMOVED 3/9/01		TAUNTON POLICE DEPARTMENT				
CCOUNT	HISTORY SUMMARY					

	•	•		EVIDENC	e# 1C Package #1	
		T Broadbane ter Test Foi		DV DENC.	E# IC TACKAGE #1	
Date	3-9-01	Corp. # Converter # Converter Type: Received From:		I-COMS	I-COMS	
Accour	1t# 43747-04			004101596 VM4000 UPS pursuant to warrant on		
Name:	Joe Amaro / Dimas Amaro					
Addres	333 Cohannet Street					
					<u>3/9/01</u>	
City:	Taunton	State/Zip Generated From:		<u>Ma. 02780</u>		
SSN#:						
	·	PPV Movies Point Test	<u>NO</u>			
						
OUTSID	E CONVERTER APPEARANCE	-	NOTE COLUMN			
<u>P</u>	Security Tabs Missing	INSIDE CONVERTER APPEARANCE				
Ī	Outside Screws Missing	ADP Module Forced Open ADP Module Cover Missing				
<u>R</u>	Converter Damaged	<u>N</u>	Scratches/Marks on Key Chips			
A	Marks Around Outside Screw	Jumper Wires Still In Place				
T	Wires Cut	T Scratches/Marks on Legs of Key Chips				
E	Tampered Codes	· .	Missing Prom#		·	
	<u>4 Po</u>	int Test				
:	Testing Point	Coe	des/Comments	5	Pass/Fail	
1.	Check Video on converter (e.g. channel	<u>P</u>		<u>ں</u> ا		
2.	5 or PPV barker on all channels.) Converter has 210 code or higher	<u> </u>				
3.	Converter has H-1 or H6 code, or tunes	<u>R</u>		N I		
4.	01-99 or 01-128 consecutively. Converter does not initialize (i.e. an					
	addressable hit)	<u>ATE</u>		T		
Of the 4	nointa hammana i di ini					
Test Com	points, how many points does it have?		•			
i ⁻	pleted On:		oject Auditor P	aul Marmelo	•	
Comments		June 25, 20	001			
comments	••	Confirmed	Pirate Device	(decoder)		
FOR OF	ICE USE ONLY:					
CONVERTER	Incharge					
CONVERTER	REMOVED 2/0/01		· .			
į.	ISTORY SUMMARY BY	Y TAUNI	ON POLICE DEPA	RTMENT		